



Fruits & Associates, Inc. 500 North Point Pkwy, Suite A Acworth, GA 30102		High-Vac Remediation (HVR) Well Manifold Assembly (Stinger Assembly)	
<i>Scale:</i> Not to scale		<i>Title:</i> Well Connection Diagram	
<i>Date:</i> February 25th, 2003		<i>Checked By:</i> John M. Fruits	
<i>Drawing By:</i> John M. Fruits		<i>Figure #:</i> 1	